

98+00

99+00

100+00

101+00

102+00

SR 46 (45 mph)

SR 46 (45 mph)

811090.2481 Strain Pole NW
99+81.20
189980.5890
50.8403 Lt
Top of Fdn 609.53

Strain Pole SW
99+33.00
50.3895 Rt
Top of Fdn 609.53
811042.4301
189986.6880

Strain Pole
101+05.00
49.7187 Lt
Top of Foundation 609.53
811213.0390
189964.9245

Strain Pole SE
100+88.80
44.6214 Rt
Top of Fdn 609.53
811196.9747
189966.9737

PSSA

Fly Station

SR 46 and Brown County Park Entrance East

Date: