

Brown County Highway Department

Monthly Update for February 5th

- : We are trying to stockpile our stone, salt and sand
- : We are spreading stone on our gravel roads using #5 mixed with #11 stone.
- : We have put up new guard rails on John Butler Rd at Hurricane Creek (approx. 75 ft of new rail). We also installed new signs for safety
- : I have been working on our bridge inventory reports
- : We have had two graders out on the gravel when needed fixing creek crossings and washed out hills
- : We are using our asphalt hot box fixing pot holes from the freeze and thaw
- : We have been washing, servicing and fixing our equipment as needed (daily)
- : We have completed our updated bridge sign list
- : Awaiting direction from the Commissioners on how to proceed with closing out insurance for wrecked Mack truck
- : We are working on plans to replace a small bridge structure on Hamilton Creek Rd. This will complete the three on Hamilton Creek Rd
- : I am in the beginning phase (design/engineering) for replacement of Bridge #91 that is on Mt Liberty Rd. USI recommended this structure to be replaced back in 2024 due to advanced deterioration.
- : I have been working on Bridge #20 project which is a superstructure replacement. Projected construction late in 2025
- : We are working on cost to fix our radios in our trucks. We have trucks without radios and radios that don't work. Our system needs work.
- : We have had positive tests for high mold count in our Highway/recycling building office that we work out of. We are working on quotes for mold remediation.

Arec Burton

Mack Truck Parts

Wheels & Tires	\$7,000
Bed lift cylinder	\$2,000
Radiator	\$700.00
Seats	\$2,000
Hydraulic parts	\$6,000
Transmission (used cost)	\$4,500
New steering shaft	\$1,000
New cab lights	
New EGR cooler	
Engine parts	
Brake system parts	
Suspension parts	
In cab controls	
Everything else	